



LIGHT  
RAIL  
TRANSIT  
AUTHORITY

19 October 2009

**MRS. YOLANDA O. RAMOS**

President  
Multi Scan Corporation  
Westwood, Eisenhower Street  
Greenhills, San Juan  
Metro Manila, Philippines 1502

**SUBJECT: Rehabilitation of MM74s by R & B SWITCHGEAR SERVICES**

Dear **Mrs. Ramos**:

I would like to start your day with the information that the Type MM74 Whipp and Bourne High Speed Circuit Breakers which were repaired, rehabilitated and restored to their original capacity by R & B Switchgear Services LTD. are operating outstandingly well.

We have been quite nervous of flash-over incidences again because of the recent and frequent occurrence of thunderstorms and lightning these past few months. But luckily, because of the modification of the no volt, there has been no flashover incidents whatsoever and we are thankful that R & B did an excellent job of rehabilitating our MM74s.

We look forward to your next project with the Authority and please extend our appreciation to R & B's excellent job done for the Manila LRTA Line 2 and to you for doing an excellent job as well.

Thank you.

Very truly yours,

**ENGR. FEDERICO J. CANAR, JR.**

OIC, Line 1 & 2 Engineering & Maintenance Department

Address:

Administration Bldg., LRTA Compound Aurora Blvd., Pasay City, M.M., Republic of the Philippines  
FAX 831-6449 • Telex 64614 LRT PN • Phones: 832-3141 to 60 / 832-0423 / 832-0432 / 831-4784 / 831-9707 / 833-2466